

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 7/21/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S01AA1015MH

Test ID: D1032-026045

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S01AA1015MH
0			Water Level	
52.29999924	02		Tap Factory Abandoned	From 4408 Liberty Heights - FIRST TAP C
52.40000153			Dye Test Visible	@ TF - downspout
52.40000153			Dye Test Not Visible	@ TF - toilet
52.40000153			General Observation	DYE SHOWS AT MH S01AA1012
52.40000153			Manhole	S01AA1007MH
52.40000153			End of Survey	DYE TEST COMPLETED
62.20000076	02	10	Obstacles Construction Debris	